


Tornado Response

April 19, 2022




NEWNAN
GEORGIA

March 25, 2021




March 25, 2021



March 26, 2021



March 26, 2021



March 26, 2021



March 26, 2021



Initial Response

- Search and Recovery
- State of Emergency
- Opening of Main Road Networks
- Critical Infrastructure Recovery



2nd Level Response

- Assessment
- Help
- Community




Impacts


- 130 Red Tagged Structures (18 Remain with no Permit)
- 214 Yellow Tagged Structures (72 Remain with no Permit)
- 652 Re-Roof Permits
- 389,764 CY Debris
- 164 stop signs, 289 street signs, 14,000 sf concrete repair
- Utilities: 167 street lights, 246 poles, 129 transformers,
142,213 feet of wire (Mutual Aid from 17 systems)

Tree Canopy

53% Loss of Tree Canopy



BEFORE



AFTER

Debris Removal



Put into Action

- Emergency Contract – Building Evaluation
- Emergency Contract – Debris Removal
- Emergency Contract – Debris Monitoring
- Relaxation of Ordinances and Procedures
- Volunteer Organization

Long Term Recovery

- FEMA – Public Assistance
- Long-Term Recovery Efforts
 - Public
 - Community
- On-Call Contracts
- Community Groups



FEMA RESPONSE

Cat	Project #	Description	Dates/Lane	Process	Submitted \$	Obligated \$
A	187862	Debris Removal P1	March 26 – May 1	Pending CRC Dev	4,243,841.62	3,191,326.97
A	187864	Debris Removal P2	May 2 – Sept 24	Submitted to PDMG 11/12	3,218,734.56	
A	435068	Debris Removal P3	Sept 25 – Nov 5+	Work to be completed		
B	187863	Emergency Protective Measures	March 26 – Nov 5	OBLIGATED 9/29		287,020.68
C	243559	Curb & Gutter	Standard	Work to be completed		
C	243560	Signs	Standard	Work to be completed		
C	435063	Road Damages	Standard	Work to be completed		
G	243304	LINC Bridge insurance	Work Complete	OBLIGATED 9/21		5,000.00 (Insurance Deductible)
G	334594	Greenville St. Statue	Work Complete	Pending Insurance Completion	40,900.00	



Questions?